

Appln No. 09/995,483
Amdt date October 1, 2010
Reply to Office action of June 1, 2010

Amendments to the Specification:

Please amend the specification as follow:

Please add the following sentence under DESCRIPTION OF THE DRAWINGS on column 2, line 60:

FIG. 15 is a partial cross-sectional bottom view of a cap according to FIG. 4 with the liner shown in FIG. 7.

Please amend the paragraph on column 4, lines 54-61 as follows:

With any of the aforementioned caps, a liner 84 may be used if necessary (FIG. 7). Typically, the liner will sit against the ridges or the grooved inner surface of the cap top portion, as for example shown in FIG. 15. To allow for venting through the liner, at least a hole ~~[[80]]~~ 86 should be formed through the liner thickness 88. The hole should preferably have a diameter between about 0.010 to 0.015 inch. The liner thickness should preferably be between about 0.015 and 0.020 inch.